

Saddle Leak - Division 2 Lot 49

In 2025 a leak was detected in Division 2. The leak was determined to not be in a cabin and could not be located by conventional means. A leak detection company was hired and used gas in the main to detect the leak location.

The leak was located at the saddle of the Division 2 Lot 49.

The leak was fixed and the since the water outflow normally registers at 0 gpm.

From:

<https://yodelinwater.org/wiki/> - **Yodelin Water**

Permanent link:

https://yodelinwater.org/wiki/leaks:2025:division_two_lot_forty-nine

Last update: **2026/07/07 21:03**

